

	Type	Hits	Search Text
1	BRS	1	10/694885
2	BRS	1	S1 and (guid\$5 spac\$3 off peal\$4 peel\$3 film\$4 slot\$3 hol\$4 inlay\$3)
3	BRS	236371	(display\$1 same (colour\$1 color\$1 led\$1))
4	BRS	39318	(display\$1 same (colour\$1 color\$1 led\$1) same panel\$1)
5	BRS	1139	(display\$1 same (colour\$1 color\$1 led\$1) same panel\$1 same cover)
6	BRS	13322	cover same layers same film\$1
7	BRS	2280232	(holes bores slits slots openings)
8	BRS	103558	(holes bores slits slots openings) near12 cover
9	BRS	72239	(layer\$1 film\$1) near12 (bright\$5 illumin\$6 lumin\$4)
10	BRS	0	S3 and S5 and S6 and S8 and S9
11	BRS	149	(S3 S4 S5) and S8 and S9
12	BRS	97	S11 and (film\$1) same (bright\$5 illumin\$6 lumin\$4)
13	BRS	72	S11 and (film\$1) near12 (bright\$5 illumin\$6 lumin\$4)
14	BRS	36	S13 and layers
15	BRS	236560	(display\$1 same (colour\$1 color\$1 led\$1))
16	BRS	39346	(display\$1 same (colour\$1 color\$1 led\$1) same panel\$1)
17	BRS	1139	(display\$1 same (colour\$1 color\$1 led\$1) same panel\$1 same cover)
18	BRS	103611	(holes bores slits slots openings) near12 cover
19	BRS	72291	(layer\$1 film\$1) near12 (bright\$5 illumin\$6 lumin\$4)
20	BRS	149	(S15 S16 S17) and S18 and S19
21	BRS	72	S20 and (film\$1) near12 (bright\$5 illumin\$6 lumin\$4)

	DBs	Time Stamp	Comments	Error Definition
1	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 17:52		
2	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:26		
3	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:36		
4	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:28		
5	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:29		
6	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:31		
7	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 14:25		
8	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:35		
9	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:40		
10	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:38		
11	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:39		
12	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:40		
13	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/23 18:41		
14	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:01		
15	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:01		
16	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:01		
17	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:16		
18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:04		
19	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:01		
20	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:01		
21	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:02		

	Errors	Ref #
1		S1
2		S2
3		S3
4		S4
5		S5
6		S6
7		S7
8		S8
9		S9
10		S10
11		S11
12		S12
13		S13
14		S14
15		S15
16		S16
17		S17
18		S18
19		S19
20		S20
21		S21

	Type	Hits	Search Text
22	BRS	36	S21 and layers
23	BRS	18	S22 and (cover same (two second))
24	BRS	14	S22 and (guid\$4 waveguid\$3 wave)
25	BRS	62	S20 and (film\$1 coat\$\$) near8 (bright\$5 illumin\$6 lumin\$4)
26	BRS	16	S25 and (light near3 guid\$4 waveguid\$3 wave near1 guid\$3)
27	BRS	11	S26 not S24
28	BRS	53783	(display\$1 same cover)
29	BRS	222055	(light near3 guid\$4 waveguid\$3 wave near1 guid\$3)
30	BRS	45002	(film\$1 coat\$4) near8 (bright\$5 illumin\$6 lumin\$4)
31	BRS	991	S30 same S32
32	BRS	1769928	cover
33	BRS	38	S33 same S34
34	BRS	37	S35 not (S24 S28)
35	BRS	858	(light near3 guid\$4 waveguid\$3 wave near1 guid\$3) adj1 plates
36	BRS	1	S32 same S34 same S37
37	BRS	8	S32 same S37
38	BRS	2	"6,448,955".pn.
39	BRS	0	S40 and (backlight\$2 cover\$3) same (lightguid\$3 guid\$3)
40	BRS	2	S40 and (backlight\$2 cover\$3) same (lightguid\$3 guid\$3 pip\$2)
41	BRS	1	S40 and (holes bores slits slots openings)

	DBs	Time Stamp	Comments	Error Definition
22	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:02		
23	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 11:05		
24	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 13:58		
25	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:18		
26	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:17		
27	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:05		
28	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:17		
29	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:43		
30	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:45		
31	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:20		
32	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:20		
33	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:21		
34	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:21		
35	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:44		
36	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:48		
37	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 12:49		
38	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 15:57		
39	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 14:12		
40	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 14:12		
41	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/05/24 14:25		

	Errors	Ref #
22		S22
23		S23
24		S24
25		S25
26		S26
27		S28
28		S29
29		S30
30		S32
31		S33
32		S34
33		S35
34		S36
35		S37
36		S38
37		S39
38		S40
39		S41
40		S42
41		S43